


d = 0,50–1,25 мм

ОТДЕЛ

ПРУЖИНЫ



d, мм	D _e , мм	D _i , мм	L _o , мм	Пружинная сталь Код товара	Нерж. сталь Код товара
0,50	3,5	2,5	1000	05/1	05/7
	4,5	3,5		05/2	05/8
	5,5	4,5		05/3	05/9
	6,5	5,5		05/4	05/10
	7,5	6,5		05/5	05/11
	8,5	7,5		05/6	05/12
0,56	3,9	2,8	1000	06/1	06/7
	5,0	3,9		06/2	06/8
	6,2	5,0		06/3	06/9
	7,3	6,2		06/4	06/10
	8,4	7,3		06/5	06/11
	9,5	8,4		06/6	06/12
0,63	4,4	3,2	1000	07/1	07/7
	5,7	4,4		07/2	07/8
	6,9	5,7		07/3	07/9
	8,2	6,9		07/4	07/10
	9,5	8,2		07/5	07/11
	10,7	9,5		07/6	07/12
0,70	4,9	3,5	1000	08/1	08/7
	6,3	4,9		08/2	08/8
	7,7	6,3		08/3	08/9
	9,1	7,7		08/4	08/10
	10,5	9,1		08/5	08/11
	11,9	10,5		08/6	08/12
0,80	5,6	4,0	1000	09/1	09/7
	6,3	4,7		09/15	09/75
	7,2	5,6		09/2	09/8
	8,8	7,2		09/3	09/9
	10,4	8,8		09/4	09/10
	12,0	10,4		09/5	09/11
0,90	13,6	12,0	1000	09/6	09/12
	6,3	4,5		10/1	10/7
	8,1	6,3		10/2	10/8
	9,9	8,1		10/3	10/9
	11,7	9,9		10/4	10/10
	13,5	11,7		10/5	10/11
1,00	15,3	13,5	1000	10/6	10/12
	6,2	4,2		11/0	11/65
	7,0	5,0		11/1	11/7
	8,0	6,0		11/15	11/75
	9,0	7,0		11/2	11/8
	11,0	9,0		11/3	11/9
1,10	13,0	11,0	1000	11/4	11/10
	15,0	13,0		11/5	11/11
	17,0	15,0		11/6	11/12
	7,7	5,5		12/1	12/7
	9,9	7,7		12/2	12/8
	12,1	9,9		12/3	12/9
1,25	14,3	12,1	1000	12/4	12/10
	15,5	13,3		12/5	12/11
	18,7	16,5		12/6	12/12
	8,8	6,3		13/1	13/7
	11,3	8,8		13/2	13/8
	13,8	11,3		13/3	13/9
1,25	16,3	13,8	1000	13/4	13/10
	18,8	16,3		13/5	13/11
	21,3	18,8		13/6	13/12

d, мм	D _e , мм	D _i , мм	L _о , мм	Пружинная сталь Код товара	Нерж. сталь Код товара	
1,40	9,8	7,0	1000	14/1	14/7	
	12,6	9,8		14/2	14/8	
	15,4	12,6		14/3	14/9	
	18,2	15,4		14/4	14/10	
	21,0	18,2		14/5	14/11	
	23,8	21,0		14/6	14/12	
1,60	11,2	8,0	1000	15/1	15/7	
	14,4	11,2		15/2	15/8	
	17,6	14,4		15/3	15/9	
	20,8	17,6		15/4	15/10	
	24,0	20,8		15/5	15/11	
	27,2	24,0		15/6	15/12	
1,80	12,6	9,0	1000	16/1	16/7	
	16,2	12,6		16/2	16/8	
	19,8	16,2		16/3	16/9	
	23,4	19,8		16/4	16/10	
	27,0	23,4		16/5	16/11	
	30,6	27,0		16/6	16/12	
2,00	13,0	9,0	1000	17/0	17/07	
	14,0	10,0		17/1	17/7	
	15,6	11,6		17/15	17/75	
	18,0	14,0		17/2	17/8	
	22,0	18,0		17/3	17/9	
	26,0	22,0		17/4	17/10	
2,25	30,0	26,0	1000	17/5	17/11	
	34,0	30,0		17/6	17/12	
	15,8	11,3		1000	18/1	18/7
	20,3	15,8			18/2	18/8
	24,8	20,3			18/3	18/9
	29,4	24,8			18/4	18/10
33,8	29,3	18/5	18/11			
38,3	33,8	18/6	18/12			
2,50	15,5	10,5	1000	19/0	19/65	
	17,5	12,5		19/1	19/7	
	19,5	14,5		19/15	19/75	
	22,5	17,5		19/2	19/8	
	27,5	22,5		19/3	19/9	
	32,5	27,5		19/4	19/10	
2,80	37,5	32,5	1000	19/5	19/11	
	42,5	37,5		19/6	19/12	
	19,6	14,0		1000	20/1	20/7
	25,2	19,6			20/2	20/8
	30,8	25,2			20/3	20/9
	36,4	30,8			20/4	20/10
42,0	36,4	20/5	20/11			
47,6	42,0	20/6	20/12			
3,20	22,4	16,0	1000	21/1	21/7	
	28,8	22,4		21/2	21/8	
	35,2	28,8		21/3	21/9	
	41,6	35,2		21/4	21/10	
	48,0	41,6		21/5	21/11	
	54,4	48,0		21/6	21/12	
3,60	25,2	18,0	1000	22/1	22/7	
	32,4	25,2		22/2	22/8	
	39,6	32,4		22/3	22/9	
	46,8	39,6		22/4	22/10	
	54,0	46,8		22/5	22/11	
	61,2	54,0		22/6	22/12	