

d = 0,4–1,2 мм

ОТДЕЛ

ПРУЖИНЫ

d, мм	D ₁ , мм	D, мм	D _e , мм	n	Вариант	L _к , мм	L _с , мм	D _d , мм	D _h , мм	R _{mr} [Nmm/°]	M _t [Nmm]	град.	M, г	Код товара	
0,4	3,9	4,3	4,7	5,00	A	3	20,0	3,5	5,5	0,06	10,56	171,1	0,11	M 04 R 20	
				5,25	B	3					0,06		179,7	0,11	M 04 R 21
				5,50	C	3					0,06		188,2	0,11	M 04 R 22
				5,75	D	3					0,05		196,8	0,12	M 04 R 23
				7,50	C	4					0,04		256,6	0,14	M 04 R 32
				8,00	A	4					0,04		273,8	0,15	M 04 R 40
				11,00	A	5					0,03		376,4	0,19	M 04 R 50
				15,00	A	7					0,02		513,3	0,24	M 04 R 60
0,5	5,9	6,4	6,9	5,00	A	3	25,0	5,0	7,5	0,10	19,63	194,0	0,23	M 05 R 20	
				5,25	B	3					0,10		203,7	0,24	M 05 R 21
				5,50	C	4					0,09		213,4	0,25	M 05 R 22
				5,75	D	4					0,09		223,1	0,26	M 05 R 23
				7,50	C	5					0,07		291,0	0,31	M 05 R 32
				8,00	A	5					0,06		310,4	0,33	M 05 R 40
				11,00	A	6					0,05		426,9	0,42	M 05 R 50
				15,00	A	8					0,03		582,1	0,55	M 05 R 60
0,7	4,5	5,2	5,9	5,00	A	5	25,0	4,0	6,5	0,48	53,88	112,6	0,40	M 07 R 10	
				5,25	B	5					0,46		118,2	0,41	M 07 R 11
				5,50	C	5					0,43		123,9	0,43	M 07 R 12
				5,75	D	5					0,42		129,5	0,44	M 07 R 13
				9,00	A	7					0,27		202,7	0,60	M 07 R 16
				9,25	B	8					0,26		208,3	0,61	M 07 R 17
				9,50	C	8					0,25		213,9	0,62	M 07 R 18
				9,75	D	8					0,25		219,6	0,64	M 07 R 19
0,7	7,2	7,9	8,6	5,00	A	5	33,0	6,5	9,5	0,31	53,88	171,1	0,58	M 07 R 20	
				5,25	B	5					0,30		179,6	0,60	M 07 R 21
				5,50	C	5					0,29		188,2	0,62	M 07 R 22
				5,75	D	5					0,27		196,7	0,63	M 07 R 23
				7,50	C	6					0,21		256,6	0,77	M 07 R 32
				8,00	A	7					0,20		273,7	0,80	M 07 R 40
				11,00	A	9					0,14		376,4	1,03	M 07 R 50
				15,00	A	12					0,10		513,2	1,33	M 07 R 60
1,0	4,5	5,5	6,5	6,00	A	8	35,0	4,0	7,0	1,57	149,23	95,0	1,08	M 10 R 10	
				6,25	B	8					1,51		99,0	1,11	M 10 R 11
				6,50	C	8					1,45		103,0	1,13	M 10 R 12
				6,75	D	8					1,40		106,9	1,16	M 10 R 13
				12,00	A	14					0,79		190,1	1,72	M 10 R 16
				12,25	B	14					0,77		194,0	1,75	M 10 R 17
				12,50	C	14					0,75		198,0	1,78	M 10 R 18
				12,75	D	14					0,74		202,0	1,80	M 10 R 19
1,0	11,5	12,5	13,5	5,00	A	7	40,0	10,5	14,5	0,83	149,23	180,0	1,72	M 10 R 20	
				5,25	B	7					0,79		189,0	1,78	M 10 R 21
				5,50	C	7					0,75		198,0	1,84	M 10 R 22
				5,75	D	7					0,72		207,0	1,90	M 10 R 23
				7,50	C	9					0,55		270,0	2,32	M 10 R 32
				8,00	A	10					0,52		288,0	2,45	M 10 R 40
				11,00	A	13					0,38		396,0	3,18	M 10 R 50
				15,00	A	17					0,28		540,0	4,15	M 10 R 60
1,2	5,5	6,7	7,9	6,00	A	9	40,0	5,0	8,5	2,67	244,29	91,4	1,84	M 12 R 10	
				6,25	B	9					2,57		95,2	1,89	M 12 R 11
				6,50	C	10					2,47		99,0	1,94	M 12 R 12
				6,75	D	10					2,38		102,8	1,99	M 12 R 13
				12,00	A	16					1,34		182,8	2,98	M 12 R 16
				12,25	B	17					1,31		186,6	3,02	M 12 R 17
				12,50	C	17					1,28		190,4	3,07	M 12 R 18
				12,75	D	17					1,26		194,2	3,12	M 12 R 19



ОТДЕЛ
ПРУЖИНЫ

d = 1,4–6,3 мм

d, мм	D _i , мм	D, мм	D _e , мм	n	Вариант	L _k , мм	L _s , мм	D _d , мм	D _h , мм	R _{mr} [Nmm/°]	M _t [Nmm]	град.	M, г	Код товара		
1,4	14,0	15,4	16,8	5,00	A	9	50,0	12,5	18,0	2,59	387,92	150,1	4,16	M 14 R 20		
				5,25	B	10					2,46		157,6	4,31	M 14 R 21	
				5,50	C	10						2,35		165,1	4,45	M 14 R 22
				5,75	D	10						2,25		172,6	4,60	M 14 R 23
				7,50	C	13						1,72		225,1	5,63	M 14 R 32
				8,00	A	13						1,62		240,1	5,92	M 14 R 40
				11,00	A	18						1,18		330,1	7,69	M 14 R 50
				15,00	A	23						0,86		450,2	10,05	M 14 R 60
2,0	8,7	10,7	12,7	7,00	A	17	45,0	8,0	14,0	11,07	1068,14	96,5	8,08	M 20 R 10		
				7,25	B	18					10,69		100,0	8,29	M 20 R 11	
				7,50	C	18						10,33		103,4	8,50	M 20 R 12
				7,75	D	19						10,00		106,8	8,71	M 20 R 13
				14,00	A	31						5,53		193,0	13,93	M 20 R 16
				14,25	B	32						5,44		196,5	14,14	M 20 R 17
				14,50	C	32						5,34		199,9	14,35	M 20 R 18
				14,75	D	33						5,25		203,3	14,56	M 20 R 19
2,0	18,5	20,5	22,5	5,00	A	13	70,0	17,0	24,5	8,09	1068,14	132,1	11,47	M 20 R 20		
				5,25	B	14					7,70		138,7	11,87	M 20 R 21	
				5,50	C	14						7,35		145,3	12,27	M 20 R 22
				5,75	D	15						7,03		151,9	12,67	M 20 R 23
				7,50	C	18						5,39		198,1	15,47	M 20 R 32
				8,00	A	19						5,05		211,3	16,27	M 20 R 40
				11,00	A	25						3,68		290,5	21,07	M 20 R 50
				15,00	A	33						2,70		396,2	27,46	M 20 R 60
2,8	23,0	25,8	28,6	5,00	A	18	90,0	21,0	31,0	24,69	2758,57	111,7	28,48	M 28 R 20		
				5,25	B	19					23,51		117,3	29,47	M 28 R 21	
				5,50	C	20						22,44		122,9	30,45	M 28 R 22
				5,75	D	20						21,47		128,5	31,44	M 28 R 23
				7,50	C	25						16,46		167,6	38,34	M 28 R 32
				8,00	A	27						15,43		178,8	40,32	M 28 R 40
				11,00	A	35						11,22		245,8	52,15	M 28 R 50
				15,00	A	47						8,23		335,2	67,93	M 28 R 60
3,6	28,0	31,6	35,2	5,00	A	24	110,0	26,0	38,0	55,08	5496,53	99,8	57,63	M 36 R 20		
				5,25	B	24					52,46		104,8	59,63	M 36 R 21	
				5,50	C	25						50,07		109,8	61,63	M 36 R 22
				5,75	D	26						47,90		114,8	63,62	M 36 R 23
				7,50	C	33						36,72		149,7	77,60	M 36 R 32
				8,00	A	34						34,43		159,7	81,60	M 36 R 40
				11,00	A	45						25,04		219,5	105,56	M 36 R 50
				15,00	A	60						18,36		299,4	137,51	M 36 R 60
4,5	27,5	32,0	36,5	5,00	A	29	120,0	25,5	39,0	132,79	10019,72	75,5	93,37	M 45 R 20		
				5,25	B	31					126,47		79,2	96,53	M 45 R 21	
				5,50	C	32						120,72		83,0	99,70	M 45 R 22
				5,75	D	33						115,47		86,8	102,86	M 45 R 23
				7,50	C	41						88,53		113,2	124,98	M 45 R 32
				8,00	A	43						83,00		120,7	131,30	M 45 R 40
				11,00	A	57						60,36		166,0	169,24	M 45 R 50
				15,00	A	75						44,26		226,4	219,81	M 45 R 60
6,3	35,0	41,3	47,6	5,00	A	41	130,0	32,5	51,0	395,26	25530,24	64,6	223,98	M 63 R 20		
				5,25	B	43					376,44		67,8	231,97	M 63 R 21	
				5,50	C	44						359,33		71,0	239,97	M 63 R 22
				5,75	D	46						343,71		74,3	247,97	M 63 R 23
				7,50	C	57						263,51		96,9	303,95	M 63 R 32
				8,00	A	60						247,04		103,3	319,95	M 63 R 40
				11,00	A	79						179,66		142,1	415,91	M 63 R 50
				15,00	A	105						131,75		193,8	543,87	M 63 R 60

Каталог пружин «Хеннлих», ноябрь 2012 года